



#### Gulfetreem G-IV Library

Airworthiness Directives 69-62-12 R1 63/21/1994

To Prevent Hazardous Deviations from the Intended Course



#### 89-02-12 R1

#### GULFSTREAM

Amendment 39-8825

Docket 93-NM-58-AD

Novises 20 89-02-12, Janedunat 39-6155.


Applicability: Modal C-IV airplanes, as listed in Culfstream Aircraft Service Change No. 110, dated January 24, 1989, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.


MOTE 1: Faragraphs (a) and (b) of this AD marely restate the requirements of paragraphs A. and B. of AD 89-02-12, Amendment 39-6155. As allowed by the phrase, "unless eccumplished previously," if those requirements of AD 89-02-12 have already been accomplished, paragraphs (a) and (b) of th is AD do not require that those actions


Figure 1B







Gulfstream G-IV Library Airworthiness Directives Selection List Cumulative Index
Description
To prevent the potential display and use
of hazardously misleading information from To prevent loss of engine power while flying
In tering containing. To prevent premature turns toward the runway while conducting ILS approaches
To prevent inadvertent pusher activation during rotation on takeoff
To ensure that the engine fire extinguishing system electrical power leads are properly connected
To prevent an airplane taking off in an unsafe takeoff configuration
Print Reverse Course
























		•	1
₹Ω	ATP - US Federal Regulatory Library History List MS041192		<u>ست</u> ر
Document ID	Title	Issue Date	
FR 49	Part 49 - Recording of Aircraft Titles and Security Documents	10/17/91	+
AC 65-19E	Inspection Authorization Study Guide	04/08/87	
AD 89-02-12	To prevent premature turns toward the runway	01/24/89	
GCSHIV-110	To prevent premature turns toward the runway	02/24/89	
GC CA IV-5	To provide a one-time inspection for identification	02/02/89	
			+
Help Navigator Boo	Nokmark Inquity Print Reverse Course List History Zoom	Graphic [	






























An Effective Date Cumulative Index  Applicable Finds  Number Date Date Description  B8-20-01 R1 02/13/89 To prevent the potential display and use of hazardously misleading information from in cing conditions  B9-02-12 04/03/89 To prevent premature turns toward the incing conditions  B9-04-10 04/03/89 To prevent madvertent pusher activation  GC SH IV-51A  B9-04-10 04/03/89 To prevent inadvertent pusher activation  GC CA IV-4  B9-05-05 05/08/89 To ensure that the engine fire extinguishing GC CA IV-4  GO 02/13/90 To prevent an airplane taking off in an unsafe GC SH IV-122  Help Mavigator Bookmark Inquiry Frink Reverse Course  List History Zoom Graphic  An History Zoom Graphic  An History Zoom Graphic  An History Zoom Graphic					1
Hondard Bookmark  Effective  Description  Description  Description  Service Information  Finds  GC SH IV-53A  of hazardously misleading information from incing conditions  D4/03/89  To prevent loss of engine power while flying  To prevent bremature turns toward the in icing conditions  To prevent inadvertent pusher activation  GC SH IV-110  runway while conducting ILS approaches  D4/03/89  To prevent inadvertent pusher activation  GC CA IV-4  during rotation on takeoff  D5/13/80  To prevent an airplane taking off in an unsafe  GC SH IV-122  takeoff configuration  Navigation	4-0		Gulfstream G-IV Library Airworthiness Directives Selection List Cumulative Index		ΨΩ
R1 02/13/89 To prevent the potential display and use of hazardously misleading information from of hazardously misleading information from of hazardously misleading information from in cing conditions  04/03/89 To prevent premature turns toward the runway while conducting ILS approaches  04/03/89 To prevent inadvertent pusher activation GC CA IV-1 during rotation on takeoff are properly connected  05/08/89 To prevent an airplane taking off in an unsafe GC SH IV-122 takeoff configuration  02/13/90 To prevent an airplane taking off in an unsafe GC SH IV-122  takeoff configuration of the confi	AD Number		Description		ord rds
05/11/81 To prevent loss of engine power while flying GC SH IV-51A in icing conditions 04/03/89 To prevent premature turns toward the runway while conducting ILS approaches 04/03/89 To prevent inadvertent pusher activation GC CA IV-4 during rotation on takeoff are extinguishing GC CA IV-5 system electrical power leads are properly connected 02/13/90 To prevent an airplane taking off in an unsafe GC SH IV-122 takeoff configuration  Nawigator Bookmark Inquiry Print Reverse Course List History Zoom Graphic Configuration	88-02-01 R1	02/13/89	To prevent the potential display and use	GC SH IV-53A	+
04/03/89 To prevent premature turns toward the runway while conducting ILS approaches 04/03/89 To prevent inadvertent pusher activation GC CA IV-4 during rotation on takeoff 05/08/89 To ensure that the engine fire extinguishing GC CA IV-5 system electrical power leads are properly connected 02/13/90 To prevent an airplane taking off in an unsafe GC SH IV-122 takeoff configuration	88-20-04	05/11/81	To prevent loss of engine power while flying in icing conditions	GC SH IV-51A	
04/03/89 To prevent inadvertent pusher activation GC CA IV-4 during rotation on takeoff 05/08/89 To ensure that the engine fire extinguishing GC CA IV-5 system electrical power leads are properly connected 02/13/90 To prevent an airplane taking off in an unsafe GC SH IV-122 takeoff configuration  Navigator Bookmark Inquiry Print Reverse Course List History Zoom Graphic A TO	89-02-12	04/03/89	To prevent premature turns toward the runway while conducting ILS approaches	GC SH IV-110	
05/08/89 To ensure that the engine fire extinguishing GC CA IV-5 system electrical power leads are properly connected  02/13/90 To prevent an airplane taking off in an unsafe GC SH IV-122 takeoff configuration  Navigator Bookmark Inquiry Print Reverse Course List History Zoom Graphic  Amongator Bookmark Inquiry Print Reverse Course List History Zoom Graphic	89-04-10	04/03/89	To prevent inadvertent pusher activation during rotation on takeoff	GC CA IV-4	
Connected  102/13/90 To prevent an airplane taking off in an unsafe GC SH IV-122 takeoff configuration  Navigator Bookmark Inquiry Print Reverse Course List History Zoom Graphic    A	89-05-05	05/08/89	To ensure that the engine fire extinguishing system electrical power leads are properly	GC CA IV-5	
Navigator Bookmark Inquiry Print Reverse Course List History Zoom Graphic	90-05-05	02/13/90	connected To prevent an airplane taking off in an unsafe takeoff configuration	GC SH IV-122	•
			Print Reverse Course List History	oom Gray	










































































<b>#</b>		Gulfetream G-IV Library		
		Airworthiness Directives Selection List Cumulative Index		ŧΩ
AD E Number	Effective Date	Description	Applicable Service Information	Word Finds
88-02-01 R1 0	02/13/89	To prevent the potential display and use of hazardously misleading information from	GC SH IV-53A	+
88-20-04 0	05/11/81	To prevent loss of engine power while flying in icing conditions	GC SH IV-51A	
89-02-12 0	04/03/89	To prevent premature turns toward the runway while conducting ILS approaches	GC SH IV-110	
89-04-10 0	04/03/89	To prevent inadvertent pusher activation during rotation on takeoff	GC CA IV-4	
89-05-05	68/80/50	To ensure that the engine fire extinguishing system electrical power leads are properly connected	GC CA IV-5	
90-05-05	02/13/90	To prevent an airplane taking off in an unsafe takeoff configuration	GC SH IV-122	+
Help Navigator	Bookmark	Inquiry Print Reverse Course List History	Zoom Graphic	




ATP - US Federal Regulatory Library   Amorthiness Directives Selection List - 04/00/92   Small Aircraft and Rotorcraft Biweekly Listing   Amorthiness Directives Selection List - 04/00/92   Small Aircraft and Rotorcraft Biweekly Listing				•	4
Iumber 92-04         Applicability           R1         Bell - Correction         39-6339         Model: 204B, 205A 205A-1, and 212 helicopters           R1         Bell - Correction         39-64-53         Model: PA-25, -25-235, and -25-260           Grob         39-6447         Model: PA-42, PA-42-720, and PA-42-720R           Piper         39-6445         Model: Jetstream HP 137 MX 1, 200, 310, and 3201           British Aerospace         39-6445         Model: Jetstream HP 137 MX 1, 200, 310, and 3201           Navigator         Polymark         Intell History         Zoom Graphic           Coss na         British Aerospace         39-6445         Model: Jetstream HP 137 MX 1, 200, 310, and 3201	41	ATP Airworthii Small A	<ul> <li>US Federal Regulatoness Directives Selection</li> <li>Vircraft and Rotorcraft Biwo</li> </ul>	ry Library List - 04/00/92 eekly Listing	7
Number 92-04           R1         Bell - Correction         39-6339         Model: 204B, 205A, 205A-1, and 212 helicopters           Piper         39-64-53         Model: PA-25, -25-235, and -25-260           Grob         39-6447         Model: PA-25, -25-235, and -25-260           Piper         39-6455         Model: PA-42, PA-42-720, and PA-42-720R           Cessna         39-6445         Model: 310, 320, 340, 401, 402, 411           British Aerospace         39-6434         Model: Jetstream HP 137 MX 1, 200, 3101, and 3201           Nawigstor         Bookmark         Inquity         Prink         Reverse Course           Model: Jetstream HP 137 MX 1, 200, 3101, and 3201         Al 1, 421         Al 1, 421	AD Number	Manufacturer	Subject	General Applicability	
R1         Bell - Correction         39-6339           Piper         39-64-53           Grob         39-6447           Piper         39-6445           Cessna         39-6445           British Aerospace         39-6434           British Aerospace         39-6434           Cessna         39-6434	Issue Numk	ser 92-04			+
Piper         39-64-53           Grob         39-6447           Piper         39-6455           Cessna         39-6445           British Aerospace         39-6434           British Aerospace         39-6434           Asvigator         Bookmark         Inquiry           Print         Print         Print	91-02-07 R1	Bell - Correction	39-6339	Model: 204B, 205A, 205A-1, and 212 helicopters	
Grob 39-6447  Piper 39-6455  Cessna 39-6445  British Aerospace 39-6434	92-04-06	Piper	39-64-53	Model: PA-25, -25-235, and -25-260	
Piper 39-6455  Cessna 39-6445  British Aerospace 39-6434  Navigator Bookmark Inquiry Print Reverse Course List	92-04-09	Grob	39-6447	ModelTwin Astie and Twin Aster Trainer, G103 Twin II, and G103A Twin II Acro gliders	
Cessna 39-6445  British Aerospace 39-6434  Navigator Bookmark Inquiry Print Reverse Course List	92-04-11	Piper	39-6455	Model: PA-42, PA-42-720, and PA-42-720R	
British Aerospace 39-6434  Navigator Bookmark Inquiry Print Reverse Course List	92-04-11	Cessna	39-6445	Model: 310, 320, 340, 401, 402, 411 414, 421	<del></del>
Navigator Bookmark Inquiry Print Reverse Course List History Zoom Grap	92-04-14	British Aerospace	39-6434	Model: Jetstream HP 137 MX 1, 200, 3101, and 3201	<u>  +</u>
		Bookmark	Reverse Course	Zoom Grap   <b>+</b>   <b>-</b>   <b>=</b>	I






						<b>◆</b>
<b>₹</b> Ω		ATP - US Federal Regulatory Library Alert Customer Bulletin Selection List Gulfstream	orary List			<b>⊕</b>
Issue Number	Issue Date	Description	Status	App ATA	Applicable ATA AD	
Gulfstre	am Aerospace	Gulfstream Aerospace Corporation - Alert Customer Bulletins	rol			+
Model 6	Model G-1159 (G-II)					
II-20	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory	26	89-02-05	
Model G	Model G-1159A (G-III)					
4-≡	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory	56	89-02-05	
W	10/01/91	Electrical power. Feeder cable inspection	Mandatory	24	91-25-05	
Model G	Model G-1159B (G-IIB)					
11-20	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory	26	89-02-05	+
E GOO	Navigator Bookmark	Inquiry Print Reverse Course List H	History Zoom	Graphic		   <sub>==</sub> }


	+ 0+	+ 10 -05	+ 10 -05 -05
משונים	ATA AD  27 89-04-10		
ATA	y 27		
C 1	ž		
Continue		Angle of a (SWC) par Fire protects	
Date	etins	1	I .
Number	Alert Cus	Alert Cus IV-4 IV-5	N-4   N-5   N-7   N-7



				•	4
₩.	ATP Sup	TP - US Federal Regulatory Library Supplemental Type Certificate Index Aircraft	Library Index	4	<i>2</i> O
Aircraft Make, Model & T.C. No.	STC No.	Description	RG.	STC Holder	
GULFSTREAM AME	ERICAN				+
G-44, AA-1, AA-1A, AA-1B, AA-5, AA-5A; T.C. A-734 A11EA, A16EA	SA308EA	Installation of A.R.P. Industries carburetor ice detection system 105AP in single and twin aircraft and single engine helicopters powered by Continental, Franklyn, and Lycoming type engines equipped with Marvel Schebler MA-2, MA-5, MA-6 and HA-6 series carburetors.	<b>ĕ</b>	Alfred R. Puccinelli Co. DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743	
G-44; T.C. A-734	SA366AL	Installation of Cessna P/N 1223000-7 and -8 wing tips.	AL	George Pappas Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501	+
Help Navigator	Sookmark Inquiry	Print Reverse Course List	History	Zoom Graphic + - E E	









ATP - US Federal Regulatory Library   Alert Customer Bulletin Selection List   Applic Gulfstream   Status   Afphic Gulfstream   Applic Boltz						•	1
Issue   Description   Status   ATA	4-0		, ರೈ	ibrary List		Ŧ	
91 G-IV  02/01/89 Angle of attack. Stall Warning Computer Mandatory 27 (SWC) part number 965-0041-035  02/02/89 Fire protection. Engine fire extinguisher Mandatory 26 system  10/01/91 Electrical power. Feeder cable Mandatory 24 inspection  10/01/91 To prevent a potential hazard caused by inability to discharge the engine or APU fire extinguisher bottles.  11/18/21 Inspection of trim tab actuators who Active 26 by inability to discharge the engine or APU fire extinguisher bottles.	Issue Number	Issue Date	Description	Status	Applicable ATA AD	ble AD	
02/01/89 Angle of attack. Stall Warning Computer Mandatory 27 (SWC) part number 965-0041-035 02/02/89 Fire protection. Engine fire extinguisher Mandatory 26 system 10/01/91 Electrical power. Feeder cable Mandatory 24 inspection  ream Aerospace Corporation - Customer Bulletins  I 4/02/79 To prevent a potential hazard caused by inability to discharge the engine or APU fire extinguisher bottles.  11/11/8/71 Inspection of time table actuators of Active 26 by inability to discharge the engine or APU fire extinguisher bottles.  13/02/79 To prevent a potential hazard caused by inability to discharge the engine or APU fire extinguisher bottles.	Model (	)-IV					+
10/01/91 Electrical power. Feeder cable Mandatory 24 inspection  10/01/91 Electrical power. Feeder cable Mandatory 24 inspection  14/02/79 To prevent a potential hazard caused by inability to discharge the engine or APU fire extinguisher bottles.  11/118/71 Instruction of trim fish actuators in Active 27 Insugator Rookmark inquiry Print Reverse Course List History Zoom Graphi	IV-4	02/01/89	Angle of attack. Stall Warning Computer (SWC) part number 965-0041-035	Mandatory		89-04-10	
10/01/91 Electrical power. Feeder cable Mandatory 24 inspection  ream Aerospace Corporation - Customer Bulletins  14/02/79 To prevent a potential hazard caused by inability to discharge the engine or APU fire extinguisher bottles.  Navigator Bookmark Inquiry Print Reverse Course List History Zoom Graph  Navigator Bookmark Inquiry Print Reverse Course List History Zoom Graph	14-5	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory		89-02-05	
d Active 26 Active 27 Active 27 Active 27	IV-7A	10/01/91	Electrical power. Feeder cable inspection	Mandatory		91-25-05	
14/02/79 To prevent a potential hazard caused Active 26 by inability to discharge the engine or APU fire extinguisher bottles.    RA	Gulstre	am Aerospace	Corporation - Customer Bulletins				
14/02/79 To prevent a potential hazard caused Active 26 by inability to discharge the engine or APU fire extinguisher bottles.  RA 11/18/71 Inspection of trim tah actuators n/n Active 27	Model (	3-159 (G-I)					
Navigator Bookmark Inquiry Print Reverse Course List History Zoom Graphi	Ξ	14/02/79	To prevent a potential hazard caused by inability to discharge the engine or APU fire extinguisher bottles.	Active		79-06-03	
	Heb Heb	118.77 Boo				72-24-04	<b>*</b>





				<b>&gt;</b>	1
<b>₽</b>	ATP Sup	TP - US Federal Regulatory Library Supplemental Type Certificate Index Aircraft	Library Index	<b>Ф.</b> Ш	
Aircraft Make, Model & T.C. No.	STC No.	Description	RG.	STC Holder	
GULFSTREAM AME	ERICAN				+
G-44, AA-1, AA-1A, AA-1B, AA-5, AA-5A; T.C. A-734 A11EA, A16EA	SA308EA	Installation of A.R.P. Industries carburetor ice detection system 105AP in single and twin aircraft and single engine helicopters powered by Continental, Franklyn, and Lycoming type engines equipped with Marvel Schebler MA-2, MA-3, MA-3SPA,MA-4, MA-4-5, MA-6 and HA-6 series carburetors.	₽ E	Alfred R. Puccinelli Co. DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743	
G-44; T.C. A-734	SA366AL	Installation of Cessna P/N 1223000-7 and -8 wing tips.	AL.	George Pappas Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501	+
Help Navigator	Bookmark Inquiry	Print Reverse Course	History	Zoom Graphic	







			<b>▼</b>
₹Ω		ATP - US Federal Regulatory Library Advisory Circular Selection List - 02/00/92	₩
lssue Number	Revised Date	Description	Subject Category
65-19E	04/00/91	Inspection Authorization Study Guide	Airmen
65-23A	07/22/87	Certification of Repairmen (Experimental Aircraft Builders	Airmen
FAA-S-8081-1A	11/00/87	Private Pilot - Practical Test Standards For Airplane, Rotorcraft, Glider, Lighter-Than-Air	Practical Test Standards
FAA-S-8081-2E	88/00/60	Commercial Pilot Practical Test Standard For Airplane, Rotorcraft, Glider, Lighter-Than-Air	Practical Test Standards
FAA-S-8081-3	04/00/89	Recreational Pilot Practical Test Standards For Airplanes (SEL, SES) and Rotorcraft (Helicopter, Gyroplane)	Practical Test Standards
FAA-S-8081-4A	03/00/88	Instrument Rating - Practical Test Standards For Airplane and Helicopter	Practical Test Standards
FAA-S-8081-5	88/00/80	Airline Transport Pilot and Type Rating - Practical Test Standards For Airplane and	Practical Test Standards ←
Help Navigator	Bookmark	Inquiry Print Reverse Course List History Z	Zoom Graphic

		1
<b>←</b> 1	ATP - US Federal Regulatory Library Advisory Circular Selection List - 02/00/92 AC 65-19E - Inspection Authorization Study Guide	ФП
Chapter/Section	tion	
	AC 65-19E - Inspection Authorization Study Guide	+
Introductory Inform	y Information	
Chapter 1	Eligibility, Issuance, Renewal, and Change of Fixed Base	
	1 Eligibility 2 Insurance 3 Duration 4 Renewal 5 Change of Fixed Base	
Chapter 2	Ten Suggestions for Taking the IA Test	
Chapter 3	Basic Functions of an IA	
den de	1 General 2 Approving Major Repairs and Major Alterations 2 Approving Major Repairs and Major Alterations	•

ed) ja



_						
<b>↑</b>	<b>₽</b>		+		<u> </u>	
		FAR Parts Effectivity	21, 36, 43, 91, 141, 147	25, 121, 135		Graphic Graphic
	ATP - US Federal Regulatory Library Federal Aviation Regulations Selection List Proposed FARs	Description	Primary Category Aircraft	Improved Access to Type III Exits		Print Reverse Course List History Zoom
	ATP Federal	Action Date	09/30/91	10/07/91		hquiry
		Fed. Reg Date	09/01/91	04/09/91		Navigator Bookmark
	₩	Docket Number	23345	26530		<b>₹</b>





4	4	:	+		+	<u></u>
_					σ	
	ATP - US Federal Regulatory Library Hazardous Materials Selection List Title 49 Subchapter C Parts 171 and 172	Topic	Parts 171 and 172 - Hazardous Materials	al Info, Regulations & Special Programs Admin, DOT	Purpose and Scope General Requirements Hazardous Waste Changes in specifications for Tank Cars Procedure Covering Tank Car Construction Matter Incorporated by Reference Definitions and Abbreviations Rules of Construction Flammable/Combustible Liquids Onboard Vessels Use of ICAO Technical Instructions Import and Export Shipments Canadian Shipments and Packaging Emergency Regulations Specification Markings Immediate Notice-Certain Hazardous Materials Incidents Datas Language	
	ATP - Haza Title 49	Section	Parts 171	General Info, Regule	103 103 104 109 109 110 111 113 114 115 115	
П	₩	Part/Subpart/Section		Part 171	A Land	

	:				4
₹Ω		ATP - Hazaı	TP - US Federal Regulatory Library Hazardous Materials Selection List Proposed Amendments		ΨŪ
Docket Number	Fed. Reg Date	Action Date	Description Eff	FAR Parts Effectivity	
0 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	20 27 20 20 20 20 20 20 20 20 20 20 20 20 20	000 0 100			+
1841 1841 1841 1841 1841 1841 1841 1841	76/11/20	26/01/20	Implementation of the international Civil 17.1 Aviation Organization's Technical Instructions	:	
HM-208	11/07/91	11/26/91	Hazardous Materials Transportation 171 Registration and Fee Assessment Program; Additional Hearing Date	·	
HM-208	10/10/91	10/21/91	Hazardous Materials Transportation 171 Registration and Fee Assessment Program;	:	
HM-166X	09/07/91	10/07/91	Transportation of Hazardous Materials; 171, Proposed Miscellaneous Amendments	171, 172	
HM-1891	10/01/90	10/01/90	Hazardous Materials Regulations: Editorial Corrections and Clarifications	171, 172	+
PH CON	Navigator Bookmark	Inquiry Print	Reverse Course List History Zoom Gra	Phic Phic	h


						<b>1</b>
фſ		ATP - US Federal Regulatory Library Orders Selection List	rary			ФŪ
Order Number	Rev.	Title	Issued By	Date	Revised Date	
2150.3A	9	Compliance and Enforcement Program	AGC-200	8812	9010	+
8020.11	13	Aircraft Accidents and Incidents -	AFS-100	2092	8712	
		Notification, Investigation, and Reporting				
8130.2B	Ξ	Airworthiness Certification of Aircraft and	AWS-200	7705	8910	
		Related Approvals				
8300.10	ω	Airworthiness Inspectors Handbook	AFS-500	8811	9011	
8400.10	വ	Air Transportation Operators Inspector's	AFS-500	8808	8006	
		Handbook				
8700.1	~	General Aviation Operations Inspector's	AFS-500	8810	9010	
		Handbook				
						+
Help Naw	Navigator E	Bookmark Inquiry Print Reverse Course List	History Zoom	Grap	ihic T	








4			+				+	
•	₩Щ							
	Gulfstream G-IV Maintenance Manual Maintenance Manual Selection List Figure References	Title	CHAPTER 32 - LANDING GEAR	ig Gear	Main Landing Gear Installation Nose Landing Gear Installation	n Gear and Doors	in Gear Ground Sa in Landing Gear- in Gear Down Lock in Gear Sequencin Filler Valve in Gear Shock Str in Landing Gear S in Landing Gear S ock Roller In in Landing Gear S ock Latch Fittin	Bookmark Indum Frint Reverse Course List History Zoom Graphic  List History Zoom Graphic
		Chapter/Section		Landing	Figure 1. Figure 2.	-0 Main	Figure 1. Figure 2. Figure 4. Figure 202 Figure 203 Figure 205 Figure 205 Figure 206 Figure 206 Figure 206	Nawigator
		Chapl		32-0		32-1		




1	۵ تهر		+		•	
•	ST.	t/Vie₩	,			
	atalog ntents	Chapter/Section/Sheet/View		32-01-01 32-01-02-A 32-01-03-C 32-01-03-C 32-01-03-E 32-01-04-F 32-01-04-F 32-01-04-H 32-03-01-04-G 32-03-01-A 32-03-01-A 32-03-01-A 32-03-01-B 32-03-01-B 32-03-01-B 32-03-03-01-B 32-03-03-01-B	32-04-01 32-04-02-A 32-04-02-B	Zoom Graphic + - =
	Gulfstream G-IV Illustrated Parts Catalog Illustrated Parts Catalog Table of Contents Chapter 32 - Landing Gear		LANDING GEAR	embly ts y)		Course List History
	Gulfstream G- Illustrated Parts ( Chapter	Part Nomenclature	CHAPTER 32 - L	Gear Installation atch Mechanism trol Valve Spring Rod Assembly Gear Sequencing Arm Pins Unit and Mounting Brackets el Assembly em and Damper Assembly tion Gear Assembly Provisions Pin (on trunnion assembly) ace Assemblies rut and Trunnion	SS	Inquiry Print Reverse Course
			· 공	Landing Gear Uplock Latch Door Control Landing Gear Locking Pins Steering Unit Nose Wheel As Valve Stem Steering and Installation Landing Gear Tie Down Prov Actuator Pin Truss Brace A Shock Strut a Piston		Navigator Bookmark
		Subject		SON	MAIN GEAR Main	£ 600







					<b>1</b>
		Gulfstream G-IV Library Aircraft Service Changes Selection List	ion List		₹Ω
Issue Number	Issue Date	Description	Status	Applicable ATA AD	Word Finds
IV-107	06/13/90	Lighting. Thrust reverser lights capsules- Replacement	Recomend	33	+
IV-108	Cancelled				
IV-109	Cancelled				
17-110	01/24/89	Auto flight. Electronic display controllers	Mandatory	22 89-02-12	12
IV-111	04/27/89	Hydraulics. Ground spoiler hydraulic plumbing - Modification	Optional	24	
IV-112	68/60/90	Electrical Power. 300 Amp transformer- Rectifier with increase voltage capability	Optional	24	
IV-112 amend 1	12/21/90	Electrical Power. 300 Amp transformer- Rectifier with increase voltage capability	Optional	24	
113	03/22/91	Flight Controls. Aileron/Spoiler input hellcrank - Luhrication provisions	Optional	27	+
₹ <b>(310</b> )	Navigator Bookmark	Inquiry Print Reverse Course List His	History Zoom	Graphic	





4















































Gulfstream  Gulfstream  tion  ust reverser lights caps  tt  Ground spoiler hydraul lodification  wer. 300 Amp transforr increase voltage cape	US Federal Regulatory Library
reverser lights ce tronic display cortions and spoiler hydra fication  1. 300 Amp transformes and Alleron/Spoiler in caste voltage ce trease voltage ce freese voltage ce freese course course course course	Alert Customer Bulletin Selection List Gulfstream
06/13/90 Cancelled Cancelled 01/24/89 04/27/89 12/21/90 12/21/90 12/21/90	Applicable Status ATA AD (red on CD
Cancelled Cancelled 01/24/89 04/27/89 12/21/90 1 03/22/91	everser lights capsules- Recomend 33
Cancelled 01/24/89 04/27/89 06/09/89 11 03/22/91 Navigator Bookmark	
01/24/89 04/27/89 06/09/89 11 03/22/91	
04/27/89 06/09/89 12/21/90 11 03/22/91	onic display controllers Mandatory 22 89-02-12
06/09/89 12/21/90 11 03/22/91 Navigator Bookmark	ınd spoiler hydraulic Optional 24 cation
12/21/90 1 03/22/91 Navigator Bookmark	300 Amp transformer-Optional 24 sase voltage capability
03/22/91  Navigator Bookmark	300 Amp transformer-Optional 24 sase voltage capability
Navigator Bookmark Inquiry Print Reverse Course	ileron/Spoiler input Optional 27
	Reverse Course List History Zoom Graphic







₹Ω		+		•	
	Manufacturer/ Model	Various		Rolls Royce Limited RRTS10-360 Series	om Graphic E
Library	Issue Date	02/00/92	12/31/91	02/27/92	History Zoom
- US Federal Regulatory Library Revision Letter Selection List	Description	February Alerts Issue 163	Aeronautical Decision Making	To prevent engine failure causedby failure of the rocker shafthold down stud	Print Reverse Course List
ATP - Re	Publisher/ Pub Category	DOT/FAA Alerts	DOT/FAA Airmen ACs	DOT/FAA Small Engine ADs	Bookmark Inquiry F
фſ	Document ID/ Revision Date	US AU 43-13 03/25/92	US AU 60-22 03/25/92	US AE 92-04-09E	Help Navigator 6











<b>)</b>	ŲΩ	ed Date	<b>→</b>	
		Last Revised Date		Graphic
	Bry			History Zoom
	latory Libr ion List		orthiness thorization tion	List T
	ATP - US Federal Regulatory Library FAA Forms Selection List		Major Repair and Alteration Malfunction or Defect Report Statement of Qualifications Application for Export Certificate of Airworthiness Mechanics Application for Inspection Authorization Airman Certificate and/or Rating Application	Reverse Course
	P-US Fer		nd Alteration Defect Reporalifications Export Certification for It	Print R.
	Ψ	4)	or Repair ar unction or D ement of Qu lication for E shanics App an Certifica an Certifica	lark Inquire
		Title	Maji Stat App Mec	igator Bookmark
		Number	337 - 8010 - 8110-14 - 8130 - 8610-1 -	Heb Mavigal











THE PARTY OF

